APPENDIX F

List of the Fatally Injured and Those Rescued from Behind the Barricade:

Following are the names of those killed in the explosion of November 5, 1930, in Mine No. 6, Sunday Creek Coal Co., near Millfield, Athens County, Ohio:

Ray Andrews	Thomas Harley	Wilbur North
Walter Andryvich	Walter Hayden	Ray Parry
Joe Bergin	John Hillen	Robert Parsons
George Brown	Charles Hoak	John Patterson
Samuel Brown	Urbin Howath	Floyd Petitt
William Brown	Ray Hunter	Thomas Peyatt
Alex Burniok	James Hurd	Wm. Peyatt
Joe Butsko	Joe Jackson	Virgil Phillips
John T. Butsko	Frank Korn	Phil Powell
Delmar Bauer	Andy Kish, Sr.	Abe Rankin
John Bauer	Andy Kish, Jr.	Vernon Roberts
Paul Burdis	George Kish	Carl Robinette
P. A. Coen	Stanley Kish	Charles Sekers
Mike Claney	William Kish	Harry Syeks
Wm. Claney	Hubert Lancaster	George Thomas
Andy Cuba	W. E. LeFever	Wm. Tytus
R. Davis	George Love	Andy Tonak
Clyde Dean	James A. Lyons	Thos. B. Trainer
Paul Ervin	John McAllister	H. H. Upson
Phil Ervin	George McClean	Alfred Wade
Silas Ervin	Earl McGee	Luther Wade
Ben Fielder	E. F. McKee	S. M. Wallace
James Gennice	Ed. McManaway	John Weis
George Green	James Martin	John Williams
Charles Grim	Wm. Messinger	Andrew Willis
Miles Grim	John Nadroski	Oscar Willis
James Handa, Sr.	James North	Virgil Willis

The 19 Men Who Were Rescued from Behind the Barricade:

The names of the 19 men who were rescued from behind the barricade, and whether they were taken to the hospital or home, is indicated as follows:

Fifteen men were taken to the Sheltering Arms Hospital,

Athens, Ohio, as follows:

Floyd Ayers   James Hunter
John Cebolo   Chris Parker
Ralph Channel   Edward Parker
Howard Davis   Carl Pickering
John Dean   James Norton
Henry Forsbaugh   James Rainaldo
James Honda   Clifford Watson
Earl Hunter

One man, Fielden Willis, was taken to the Cherrington Hospital at
Logan, Ohio. Three men were taken to their homes, namely, Floyd
Crabtree, Robert Cobb, and Harold Phillips. Phillips is the man
who walked out without assistance.