

COAL FATALITY  
REPUBLIC STEEL CORPORATION  
UNSPECIFIED MICHIGAN MINE  
JAN. 1, 1948

A miner was killed when a counterweight became detached from the upper section fell in the counterweight compartment to the bottom of the shaft shattered the protective blocking and struck him.