

6 BURIED MINERS SAVED

Workers at Oronogo, Mo., Are Rescued When Hole is Blasted Through to Them.

Webb City, Mo., Nov. 8.—A cave-in, caused by an overloaded mill hopper, caused six men to be buried alive in the Needmore zinc mine at Oronogo, but they were rescued soon afterward when a hole was blasted through to them. The pumps were disabled by the crash of earth, which took down the mill and all machinery.

The mine is operated by J. H. Magee and John Newland of Carthage.

1911 Six miners rescued from cavein at Needmore Zinc mine

Clipped By:



usmra_rob

Sun, May 23, 2021