## COAL FATAL

## BUREAU OF MINES

SUBJECT: Mine explosion at the A Quarry, Nazareth, Pennsylvania, April 13, 1910, eleven men were killed.

A mine explosion at the A Quarry, Nazareth, Pennsylvania, April 13, 1910 caused the death of eleven men.

[M.W. Vol. 34, P. 131]

6-615 d ACCIDENTS DUE T	O EXPLOSIVES (6).
Name of mine H Charry	Date Hpr. 13, 1910
Name of mine . H Quarry Location	Vennsylvama Hour
Operator	
Handling and transportation	Returned too soon  Delayed blast
Handling caps, detonators, squibs, and fuse	Delayed blast
Thawing explosives	Shot breaking through pillar or rib
Tamping	Suffocation by powder gas
Premature blast and short fuse	Striking unexploded charge in removing débris
Blown out or windy shot	Drilling into unexploded charge
Flying pieces of rock or coal	Miscellaneous
Immediate cause 11 Explosion"	M.W. Val. 34, p.131
Number killed Injured	Occupation
Character of injury	Nationality
State Inspector's report, page; year ending	