

1906 Haverstraw Clay landslide NEWS4

Clipped By: usmra_rob Jul 8, 2025 The landslide which earried away the thirteen houses was caused by the falling in of the bank under which the excavators of the brick manufacturers had been working for a number of years. The ground began cracking and showing seams at noon yesterday and some of the occupants of houses along the brink took warning and left. Others believed that nothing serious would happen and remained.

When the breakage occurred in the long line of land which formed the ragged edge of Rockland street, one house toppled over into the pit with all who were living within its walls. The other occupants of the houses prepared to leave their homes in the face of a blinding snow starm. A number of people who lived nearby rushed to their aid and were assisting them in getting out when twelve more houses went down, carrying with them not only the families who occupied them, but also several of those who had gone to their assistance. Overturned stoves set fire to the buildings and firemen came from miles around, but when the landslide occurred it broke the water main, thus cutting off the entire supply.

To-night relatives and friends of those burled beneath the ruins are still watching, as they have been all day, for the bodies of the dead to be brought out.

James Sammie, who lived along the edge of the pit, did not get out of his house until it had settled eight feet. All the rest of the family escaped but his wife, and she went down with the building. Mr. Sammie obtained ropes and went down after his wife, bringing her up with the aid of two men. Her leg was broken in the fall, but she suffered no other injury.

1906 Haverstraw Clay landslide NEWS4