8 MEN KILLED IN ADRIAN MINE Terrible Mishap at Big Colliery When Powder Explosion Took Place. RESCUERS ARE AT WORK Bodies Recovered Last Night; Two Missing. An explosion and resultant fire, believed to have been caused by blasting powder secreted into the Adrian slope mine of the Rochester and Pittsburgh Coal and Iron Company at Adrian, occurred shortly after eight o'clock yesterday morning, and at eleven o'clock last night eight miners were unaccounted for. The list of dead is as follows: MIKE SCARPING, married. SAMUEL BONSANTIE, married. LOBERT SCARLOTTE, single. LEWIS SACK, married. MIKE BEHINNIS, married. PAUL SINOSKI, single. PETER REITZ, married, son-in-law of ALFONSO DELLIVERE, married. Four other men were rescued in an unconscious condition and taken to the surface where they were resuscitated by a first aid corps. They were Anthony Goodlock, Porenzo Fornio, Mike Zuby and Angelo Fornio. All will live. Mine Inspector Thomas A. Furniss and T. S. Lowther, of Punxsutawney, and Elias Philips, of DuBois, were quickly on the scene and headed rescuing crews. Their preliminary investigation showed that there was evidently an explosion in the mine and that a fire was following it. At midnight officials of the Adrian mine of the R. & P. C. & I. Co., notified the public that six bodies had been located by the rescuing crew working under the mine inspectors. time, the crew of the Mine Rescue Car from Pittsburg had just joined the rescuers in searching for the bodies of two more men who are missing, and known to be in the mine. The six bodies recovered have not been brought to the surface nor have they been identified. They were all in good condition, death evidently having been caused by after-damp. They will not be brought out until the remaining bodies are found and then identifica-tions will be established. The Adrian mine is one of the largest slope mines in this section of the coun-It is considered a gaseous mine but the air has always been of a high quality. The extent of damage to the workings done by the explosion cannot be determined for hours and perhaps days yet. However, it is not believed that the interior will be disturbed in any other than the ninth right series, where the explosion occurred.

1911 Adrian Mine explosion NEWS1