

150 Miners Rescued From Burning Shaft

Peoria, Ill., Nov. 3.—One hundred and fifty miners were rescued from the Crescent mine near here this afternoon after fire had trapped them for more than an hour. The fire was caused by a spark from a circuit breaker. The miners were freed by an escapement in another part of the mine. Several were overcome by smoke. Considerable damage was done to the mine.

1920 One hundred fifty miners rescued from fire in Crescent mine

