

LIST OF MEN ~~KILLED~~ IN THE TWO EXPLOSIONS

FIRST EXPLOSION

	NAME	OCCUPATION	REMARKS
1	Emil Silfast	Timberman helper	
2	John Ikonen	Rollerman	
3	P. A. Boyd	Pumper	
4	Tom Flint	Mason	
5	Ben Barry	Gas Watch.	Body found
6	R. Warburton	Boss Driver	Body found
7	Gus Rainey	Rope Runner	
8	Pete Monson	Pipeman	Body found
9	Robt. Herron	Gas Watch	
10	W. H. Pascoe	" "	
11	Jack Rimmer	" "	
12	Harvey Lyon	" "	
13	Gabe Lahti	Timberman	
14	Alexander Briggs	Supt. Hanna Camp	
15	Joseph Burton	Foreman No. 1 Mine	
16	J. B. Evans	Gas Watch	
17	James Knox	" "	Foreman No. 3 Mine
18	Alfred Dodds	Foreman No. 2 Mine	

SECOND EXPLOSION

19	A. Madden	Shot Firer	
20	Jas. Tyner	Miner	
21	T. D. Penn	"	
22	Elmer Johnson	"	
23	Wm. Joki	"	
24	Alex. Tennent	Driver	Body found
25	A. C. Corly	Miner	
26	Chas. Harris	Pumper	
27	Emil Hendrickson	Driver	
28	Jalmer Ollila	Miner	
29	Jonas A. Lynn	Driver	
30	Abel Pura	"	
31	Tony Dodds	Boss Driver	
32	C. X. Hughes	Miner	
33	Henry Foster	Laborer inside	
34	Mat Joki	Miner	
35	Jno. Cookson	Driver	
36	Alfred Halliday	Laborer	
37	Jim Larson	Shot Firer	
38	A. Riley	Driver	
39	Wm. Johnson	Shot Firer	

40	Mat. Huhtala	McGinty Man	Body found
41	Geo. Case	Boiler Man	
42	John Hay	Miner	
43	Andrew Hay	Miner	
44	Henry G. Birchall	"	
45	Andrew Birchall	"	
46	D. Wilson	Timberman	
47	Sam McCormick	Laborer inside	
48	B. L. Frink	Pumper	
49	Pete Travis	Trackman	
50	James Smeaton	Shot Firer	
51	Wm. Burns	Laborer inside	
52	Jno. Tully	" "	
53	Jno. Tate	Shot Firer	
54	D. M. Elias	Wyo. State Mine Inspector, No. 1 Dist.	
55	Frank Collins	Miner	
56	Aug. Lakson	"	
57	Eusti Harrikka	"	
58	Robt. Armstrong	U. P. Signalman	
59	F. C. Burton	Trackman	

ANALYSIS OF COAL TAKEN FROM EAST SIDE

OF No. 1 MINE

Moisture,	6.38
Volatile Matter	48.43
Fixed Carbon	36.37
Ash	<u>8.82</u>
	100.00