

TABLE 4.—Fatal Accidents Inside and Outside of Mines

Date	Name of Person	Nationality	Occupation	Age	Married or single	Number of widows	Number of orphans	Name of Mine	County	Nature and Cause of Accident in Brief
April 16	Martin Tyrez,	Polish,	Miner,	36	M	1	1	Haws No. 3,	Somerset, ...	Instantly killed by fall of rock while scrap- ing from a mining machine that was being used to make the first cut into the side of the heading, for a room neck.
May 14	Frank Bombah,	Austrian, ...	Miner,	35	S.	Morrellville No. 4, ...	Cambria, ...	Instantly killed by fall of rock while under- mining coal at face of heading. A slip in the rock close to the edge of the coal caused the piece to fall.
	Charles Stephein, ...	Polish, ...	Driver,	25	M.	1	4	Smokeless No. 1,	Cambria, ...	Killed by an explosion of gas and dust.
	Valentine Sheschal, ...	Polish,	Driver,	32	M.	1	1			
	Charles F. Mays, ...	American, ...	Driver,	32	M.	1	1			
	John Hoffman,	German,	Miner,	32	S.			
24	Jacob Wolf,	German,	Miner,	24	M.	1			
	James Evans,	American, ...	Rope-rider, ...	25	M.	1	1			
	David Evans,	American, ...	Miner,	27	M.	1	1			
	Edward Evans,	American, ...	Miner,	49	M.	1			
	Gomer Phillips,	American, ...	Rescuer, ...	30	M.	1			
June 3	Jacob Satilsowski, ...	Polish,	Miner,	29	S.	Eureka No. 40,	Cambria, ...	Killed by being thrown from an empty mine car that was derailed at a parting, while being hauled out the mine.
	26 Digninski Sebastine, ..	Italian,	Miner,	33	M.	1	2	Morrellville No. 1, ...	Cambria, ...	Instantly killed by fall of rock while under- mining coal in heading stump.
Aug. 6	Joseph Baber,	Austrian, ...	Miner,	20	S.	Eureka No. 40,	Cambria, ...	Fatally injured by fall of coal and bone while undermining coal at face of room. Died two days later.
Sept. 3	John Baron,	Slavonian, .	Miner,	42	M.	1	6	Eureka No. 42,	Cambria, ...	Instantly killed by fall of slate while mak- ing preparations to put a prop under it.
Oct. 9	Leslo Kerula,	Austrian, ...	Miner,	53	M.	1	4	Eureka No. 40,	Cambria, ...	Instantly killed by fall of coal that he was undermining at face of room.
	26 Stephen Benko,	Austrian, ...	Timberman	22	S.	Eureka No. 35,	Somerset, ...	Instantly killed by fall of rock on main heading at a parting while making a place to set timber under rock.

*An account of this accident is given in the preliminary part of the report.