Preliminary Report of Accident

U.S. Department of Labor Mine Safety and Health Administration



PR001 07/25/2024

1. Accident Type F - Fatal Injury	2. Accident Classification 12 - Powered Haulage	3. Date/Time of Accident 07/12/2024 11:10 PM		4. Date/Time of Death 07/23/2024 8:18 PM		5. Fatal Case No FAI-F00D54E-1	
6. Mine Information a) Mining Company Name: b) Mine Name: c) Parent of Mining Company	Pocahontas Coal Company, Wyco Surface Mine : Metinvest B V	LLC					
7. Mine Location Information a) City BECKLEY		8. Mine ID Num State 46-09627		ber 9. Unio			
10. Primary Mineral Mined Bituminous Coal And Lignite Surface Mining		11. Number of E a) Total 50	mployees b) Undergroun	d c) Open Pit/Quarry	y	d) Mill/Prep Plant	e) Other
12. Contractor Name				13. Contractor Union		14. Contractor ID N	umber
15. Contractor Address a) City	b) County	c) State		d) Zip Code			
16. Number of Contractor Empl a) Total	oyees b) Underground	c) Open P	Pit/Quarry	d) Mill/Pr	ep Plant		e) Other
17. Number of Persons in Mine at Time of Accident a) Mine Employees b) Contractor Employees 20		18. Number of P	ersons Unaccou oyees	nted for b) Contractor Employees			
19. Accident Location 03 - Open Pit						20. Mining Height Feet Inches	
21. Nonfatal Injuries	22. Fatal Injuries						
a) First Name Ashley	a) MI a) Last Name Cogar		gular Job Title ck Driver	d) Activity at Time of Acc Walking to truck	ident	Employee Mine Employee	,
	Cogar b) Experience at the Mine	34 Tru	ck Driver		d) Expe		
Ashley 24. Mining Experience a) Total Experience 1 Years 48 Weeks 0	Cogar b) Experience at the Mine	c) Experience at the	ck Driver	Walking to truck	d) Expe	Mine Employee	
Ashley 24. Mining Experience a) Total Experience 1 Years 48 Weeks 0 Days	Cogar b) Experience at the Mine 0 Years 17 Weeks 0 Days	c) Experience at the	ck Driver	Walking to truck	d) Expe	Mine Employee	
Ashley 24. Mining Experience a) Total Experience 1 Years 48 Weeks 0 Days 25. Autopsy Performed 26. Mine Telephone No. (304) 774-0199 27. Description of Accident (inc	Cogar b) Experience at the Mine 0 Years 17 Weeks 0 Days	c) Experience at th 0 Years 17 Week	ne Activity at the cs 0 Days	Walking to truck Time of the Accident I recovery operations)	d) Expo	Mine Employee erience with Contract ears Weeks Days	
24. Mining Experience a) Total Experience 1 Years 48 Weeks 0 Days 25. Autopsy Performed 26. Mine Telephone No. (304) 774-0199 27. Description of Accident (inc. A truck driver was seriously in	b) Experience at the Mine 0 Years 17 Weeks 0 Days If Yes, Location	c) Experience at th 0 Years 17 Week	ne Activity at the (s 0 Days e, and status and On July 23, 2024	Walking to truck Time of the Accident I recovery operations) , the truck driver died from he	d) Expe Ye	Mine Employee erience with Contract ears Weeks Days	or
24. Mining Experience a) Total Experience 1 Years 48 Weeks 0 Days 25. Autopsy Performed 26. Mine Telephone No. (304) 774-0199 27. Description of Accident (inc. A truck driver was seriously in. The information provided in the	b) Experience at the Mine 0 Years 17 Weeks 0 Days If Yes, Location Slude equipment involved, the exact jured after being struck by the bucket of	c) Experience at th 0 Years 17 Week	ne Activity at the (s 0 Days e, and status and On July 23, 2024	Walking to truck Time of the Accident I recovery operations) , the truck driver died from he	d) Expe Ye	Mine Employee erience with Contract ears Weeks Days	or
Ashley 24. Mining Experience a) Total Experience 1 Years 48 Weeks 0 Days 25. Autopsy Performed 26. Mine Telephone No. (304) 774-0199 27. Description of Accident (inc. A truck driver was seriously in. The information provided in the thecause of the accident. 28. Equipment Manufacturer	b) Experience at the Mine 0 Years 17 Weeks 0 Days If Yes, Location Slude equipment involved, the exact jured after being struck by the bucket of	c) Experience at th 0 Years 17 Week location in the mine f a front-end loader. ONLY and does not if 29. Model 993K 32. Field Office	ne Activity at the (s 0 Days e, and status and On July 23, 2024	Walking to truck Time of the Accident I recovery operations) , the truck driver died from he termination regarding the nati	d) Expe Ye	Mine Employee erience with Contract ears Weeks Days	or
Ashley 24. Mining Experience a) Total Experience 1 Years 48 Weeks 0 Days 25. Autopsy Performed 26. Mine Telephone No. (304) 774-0199 27. Description of Accident (inc. A truck driver was seriously in. The information provided in the thecause of the accident. 28. Equipment Manufacturer Caterpillar 30. District	b) Experience at the Mine 0 Years 17 Weeks 0 Days If Yes, Location Slude equipment involved, the exact jured after being struck by the bucket of	c) Experience at th 0 Years 17 Week location in the mine f a front-end loader. ONLY and does not if 29. Model 993K 32. Field Office	e, and status and On July 23, 2024	Walking to truck Time of the Accident I recovery operations) , the truck driver died from he termination regarding the nati	d) Expe Ye	Mine Employee erience with Contract ears Weeks Days incident or conclusion.	or
Ashley 24. Mining Experience a) Total Experience 1 Years 48 Weeks 0 Days 25. Autopsy Performed 26. Mine Telephone No. (304) 774-0199 27. Description of Accident (inc A truck driver was seriously in The information provided in the thecause of the accident. 28. Equipment Manufacturer Caterpillar 30. District C1200 - Pineville District 34. Accident Investigator First Name	b) Experience at the Mine 0 Years 17 Weeks 0 Days If Yes, Location Ilude equipment involved, the exact jured after being struck by the bucket on is notice is based on preliminary data.	c) Experience at th 0 Years 17 Week location in the mine f a front-end loader. ONLY and does not if 29. Model 993K 32. Field Office	e, and status and On July 23, 2024	Walking to truck Time of the Accident I recovery operations) , the truck driver died from he termination regarding the nate	d) Expe Ye	Mine Employee erience with Contract ears Weeks Days incident or conclusion.	or
24. Mining Experience a) Total Experience 1 Years 48 Weeks 0 Days 25. Autopsy Performed 26. Mine Telephone No. (304) 774-0199 27. Description of Accident (inc A truck driver was seriously in The information provided in the thecause of the accident. 28. Equipment Manufacturer Caterpillar 30. District C1200 - Pineville District 34. Accident Investigator First Name Aaron 35. MSHA Person Notified First Name	b) Experience at the Mine 0 Years 17 Weeks 0 Days If Yes, Location Flude equipment involved, the exact jured after being struck by the bucket on its notice is based on preliminary data of the provided in	c) Experience at th 0 Years 17 Week location in the mine f a front-end loader. ONLY and does not in 29. Model 993K 32. Field Office C1201 - Pinex	e, and status and On July 23, 2024 represent final det ville WV Field Offit Date/Time Not 07/13/2024 12:	Walking to truck Time of the Accident I recovery operations) , the truck driver died from he termination regarding the nate	d) Expe Ye	Mine Employee erience with Contract ears Weeks Days incident or conclusion.	or

Woman Dies in West Virginia's Second Reported Coal Mining Fatality of 2024

A West Virginia woman has died after an accident at a southern West Virginia coal mine
By Associated Press

July 24, 2024, at 3:30 p.m.

CHARLESTON, W.Va. (AP) — A West Virginia woman died Wednesday more than a week after an accident at a southern West Virginia coal mine, Gov. Jim Justice said.

Ashley Cogar, 33, of Erbacon, was injured at the Wyco Surface Mine, near the border of Raleigh and Wyoming counties, Justice said in a news release.

"Our miners are true heroes, providing the essential work needed to energize and power steel-making in our country and worldwide," Justice said. "Without them, we wouldn't be able to live as we do, and their efforts deserve our utmost respect. Unfortunately, this tragic loss highlights the daily risks our fearless miners face."

The July 12 accident involved power haulage, which is equipment such as shuttle cars, scoops, locomotives and front end loaders, according to the U.S. Mine Safety and Health Administration.

Further details of the accident, which is under investigation by the Mine Safety and Health Administration and the state Office of Miners' Health Safety and Training, were unavailable, said Andy Malinoski, a spokesperson for the state Department of Homeland Security.

According to MSHA, the mine is operated by Pocahontas Coal Co. LLC and controlled by Metinvest, a worldwide supplier of raw materials and steel products based in The Netherlands.

It was the second reported coal fatality of the year in West Virginia and the fourth nationally, according to the Mine Safety and Health Administration. There were nine such U.S. deaths last year.

The employment of women in the mining industry in general is rare. According to the U.S. Bureau of Labor Statistics, an estimated 15% of the industry's workers were women in 2021, the latest year available. It didn't provide a breakdown of employment by gender in coal mining.

https://www.usnews.com/news/best-states/westvirginia/articles/2024-07-24/woman-dies-in-west-virginias-secondreported-coal-mining-fatality-of-2024