

APPENDIX A



Section A—Victim Data

1. Name	2. Sex	3. Social Security Number
Harold Joseph Boyd (Injured)	<input checked="" type="checkbox"/> Male <input type="checkbox"/> Female	226-96-7499
4. Age	5. Job Classification	
25	Roof Bolting Machine Operator	
6. Experience at this Classification	7. Total Mining Experience	
4 years	4½ years	
8. What activity was being performed at time of accident?	9. Victim's Experience at this Activity	10. Was victim trained in this task?
Roof Bolting	4 years	Yes

Section B—Victim Data for Health and Safety Courses/Training Received (related to accident)	Date Received
11.	
Annual Refresher Training (Including Hazard Recognition, Self	12/82
12.	
Rescue Devices, Mine Gases and Ventilation)	
13.	
14.	

Section C—Supervisor Data (supervisor of victim)	
15. Name	16. Certified
Ernest Hall	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No
17. Experience as Supervisor	18. Total Mining Experience
8 months at McClure No. 1 Mine	8 years

Section D—Supervisor Data for Health and Safety Courses/Training Received (related to accident)	Date Received
19.	
Annual Certified Persons Training	6/83
20.	
21.	
22.	

23. When was the supervisor last present at accident scene prior to the accident?	24. What did he do when he was there?
-Present at time of accident	Unknown (he was killed in the explosion).

25. When was he last in contact with the victim?	26. Did he issue instructions relative to the accident?
Unknown	N/A
27. Was he aware of or did he express an awareness of any unsafe practice or condition?	
N/A	



Section A—Victim Data

1. Name Mary Kathleen Counts 2. Sex Male Female 3. Social Security Number 212-30-7658

4. Age 51 5. Job Classification Shuttle Car Operator
 6. Experience at this Classification _____ 7. Total Mining Experience _____

8. What activity was being performed at time of accident? 1-3/4 months 9. Victim's Experience at this Activity 2½ years 10. Was victim trained in this task? _____

Installing auxiliary fan tubing 1-3/4 months Yes

Section B—Victim Data for Health and Safety Courses/Training Received (related to accident)	Date Received
11. _____	_____
<u>Annual Refresher Training (Including Hazard Recognition, Self</u>	<u>12/82</u>
<u>Rescue Devices, Mine Gases and Ventilation)</u>	_____
12. _____	_____
13. _____	_____
14. _____	_____

Section C—Supervisor Data (supervisor of victim)

15. Name Ernest Hall 16. Certified Yes No

17. Experience as Supervisor 8 months at McClure No. 1 Mine 18. Total Mining Experience 8 years

Section D—Supervisor Data for Health and Safety Courses/Training Received (related to accident)	Date Received
19. _____	_____
<u>Annual Certified Persons Training</u>	<u>6/83</u>
20. _____	_____
21. _____	_____
22. _____	_____

23. When was the supervisor last present at accident scene prior to the accident? Present at time of accident 24. What did he do when he was there? Unknown (he was killed in the explosion)

25. When was he last in contact with the victim? Unknown 26. Did he issue instructions relative to the accident? N/A

27. Was he aware of or did he express an awareness of any unsafe practice or condition? N/A



Section A—Victim Data

1. Name <u>Covey Jack French</u>		2. Sex <input checked="" type="checkbox"/> Male <input type="checkbox"/> Female	3. Social Security Number <u>230-46-5062</u>
4. Age <u>45</u>	5. Job Classification <u>Continuous Mining Machine Operator</u>		7. Total Mining Experience <u>19 years</u>
6. Experience at this Classification <u>16 years</u>		8. What activity was being performed at time of accident? <u>Installing auxiliary fan tubing</u>	9. Victim's Experience at this Activity <u>16 years</u>
		10. Was victim trained in this task? <u>Yes</u>	

Section B—Victim Data for Health and Safety Courses/Training Received (related to accident)	Date Received
11. Annual Refresher (Including Hazard Recognition, Self Rescue	12/82
12. Devices, Mine Gases and Ventilation)	
13.	
14.	

Section C—Supervisor Data (supervisor of victim)

15. Name <u>Ernest Hall</u>	16. Certified <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No
17. Experience as Supervisor <u>8 months at McClure No. 1 Mine</u>	18. Total Mining Experience <u>8 years</u>

Section D—Supervisor Data for Health and Safety Courses/Training Received (related to accident)	Date Received
19. Annual Certified Persons Training	6/83
20.	
21.	
22.	

23. When was the supervisor last present at accident scene prior to the accident? <u>Present at time of accident</u>	24. What did he do when he was there? <u>Unknown (he was killed in explosion).</u>
---	---

25. When was he last in contact with the victim? <u>Unknown</u>	26. Did he issue instructions relative to the accident? <u>N/A</u>
27. Was he aware of or did he express an awareness of any unsafe practice or condition? <u>N/A</u>	



Section A—Victim Data

1. Name <u>Ernest Avery Hall</u>	2. Sex <input checked="" type="checkbox"/> Male <input type="checkbox"/> Female	3. Social Security Number <u>226-78-6010</u>
4. Age <u>30</u>	5. Job Classification <u>Section Foreman</u>	
6. Experience at this Classification <u>8 months at McClure No. 1 Mine</u>		7. Total Mining Experience <u>8 years</u>
8. What activity was being performed at time of accident? <u>Supervising Section</u>		
9. Victim's Experience at this Activity <u>8 months at the McClure No. 1 Mine</u>		10. Was victim trained in this task? <u>Yes</u>

Section B—Victim Data for Health and Safety Courses/Training Received (related to accident)	Date Received
11. <u>Annual Certified Persons Training</u>	<u>6/9/83</u>
12.	
13.	
14.	

Section C—Supervisor Data (supervisor of victim)

15. Name <u>Ronald Sluss</u>	16. Certified <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No
17. Experience as Supervisor <u>4½ years</u>	18. Total Mining Experience <u>10 years</u>

Section D—Supervisor Data for Health and Safety Courses/Training Received (related to accident)	Date Received
19. <u>Annual Certified Persons Training</u>	<u>12/82</u>
20.	
21.	
22.	

23. When was the supervisor last present at accident scene prior to the accident? <u>6/21/83 - 7:45 p.m.</u>	24. What did he do when he was there? <u>Assisted Earnest Hall, Forrest Riner, Jr., and Luther McCoy in repairing conveyor belt feeder chain.</u>
25. When was he last in contact with the victim? <u>6/21/83 - 7:45 p.m.</u>	26. Did he issue instructions relative to the accident? <u>Informed Hall to have coal rib corners bolted.</u>
27. Was he aware of or did he express an awareness of any unsafe practice or condition? <u>No</u>	



Section A—Victim Data

1. Name		2. Sex		3. Social Security Number	
<u>Emmery Allen Howard (Injured)</u>		<input checked="" type="checkbox"/> Male <input type="checkbox"/> Female		230-76-2110	
4. Age		5. Job Classification		7. Total Mining Experience	
30		Miner Helper		3½ years	
8. What activity was being performed at time of accident?			9. Victim's Experience at this Activity		10. Was victim trained in this task?
Miner Helper			1 year		Yes

Section B—Victim Data for Health and Safety Courses/Training Received (related to accident)

	Date Received
11. Annual Refresher Training (Including Hazard Recognition, Self	12/82
12. Rescue Devices, Mine Gases and Ventilation)	
13.	
14.	

Section C—Supervisor Data (supervisor of victim)

15. Name		16. Certified	
<u>Ernest Hall</u>		<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	
17. Experience as Supervisor		18. Total Mining Experience	
<u>8 months at McClure No. 1 Mine</u>		<u>8 years</u>	

Section D—Supervisor Data for Health and Safety Courses/Training Received (related to accident)

	Date Received
19. Annual Certified Persons Training	6/83
20.	
21.	
22.	

23. When was the supervisor last present at accident scene prior to the accident?	24. What did he do when he was there?
<u>Present at time of accident.</u>	<u>Unknown (he was killed in the explosion).</u>

25. When was he last in contact with the victim?	26. Did he issue instructions relative to the accident?
<u>Unknown</u>	<u>N/A</u>
27. Was he aware of or did he express an awareness of any unsafe practice or condition?	
<u>N/A</u>	



Section A—Victim Data

1. Name Luther Julian McCoy 2. Sex Male Female 3. Social Security Number 347-36-6037

4. Age 37 5. Job Classification Repairman

6. Experience at this Classification 14 years 7. Total Mining Experience 16 years

8. What activity was being performed at time of accident? Departing from the 2 Left Section 9. Victim's Experience at this Activity 14 years 10. Was victim trained in this task? Yes

Section B—Victim Data for Health and Safety Courses/Training Received (related to accident)

	Date Received
11. <u>Newly Employed Experienced Miner Training (Including Hazard</u>	<u>1/10/83</u>
12. <u>Recognition, Self Rescue Devices, Mine Gases and Ventilation)</u>	
13. <u>Electrical Qualification Retraining</u>	<u>6/09/83</u>
14.	

Section C—Supervisor Data (supervisor of victim)

15. Name Ernest Hall 16. Certified Yes No

17. Experience as Supervisor 8 months at McClure No. 1 Mine 18. Total Mining Experience 8 years

Section D—Supervisor Data for Health and Safety Courses/Training Received (related to accident)

	Date Received
19. <u>Annual Certified Persons Training</u>	<u>6/83</u>
20.	
21.	
22.	

23. When was the supervisor last present at accident scene prior to the accident? Present at time of accident.

24. What did he do when he was there? Unknown (he was killed in the explosion).

25. When was he last in contact with the victim? Unknown 26. Did he issue instructions relative to the accident? N/A

27. Was he aware of or did he express an awareness of any unsafe practice or condition? N/A



Section A—Victim Data

1. Name <u>Eugene Walton Meade</u>	2. Sex <input checked="" type="checkbox"/> Male <input type="checkbox"/> Female	3. Social Security Number <u>230-92-9457</u>
4. Age <u>27</u>	5. Job Classification <u>Shuttle Car Operator</u>	
6. Experience at this Classification <u>1 year</u>	7. Total Mining Experience <u>7 years</u>	
8. What activity was being performed at time of accident? <u>Installing auxiliary fan tubing</u>	9. Victim's Experience at this Activity <u>1 year</u>	10. Was victim trained in this task? <u>Yes</u>

Section B—Victim Data for Health and Safety Courses/Training Received (related to accident)

11.	Date Received
<u>Annual Refresher (Including Hazard Recognition, Self Rescue</u>	<u>12/82</u>
<u>Devices, Mine Gases and Ventilation)</u>	
13.	
14.	

Section C—Supervisor Data (supervisor of victim)

15. Name <u>Ernest Hall</u>	16. Certified <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No
17. Experience as Supervisor <u>8 months at McClure No. 1 Mine</u>	18. Total Mining Experience <u>8 years</u>

Section D—Supervisor Data for Health and Safety Courses/Training Received (related to accident)

19.	Date Received
<u>Annual Certified Persons Training</u>	<u>6/83</u>
20.	
21.	
22.	

23. When was the supervisor last present at accident scene prior to the accident? <u>Present at time of accident</u>	24. What did he do when he was there? <u>Unknown (he was killed in the explosion)</u>
---	--

25. When was he last in contact with the victim? <u>Unknown</u>	26. Did he issue instructions relative to the accident? <u>N/A</u>
--	---

27. Was he aware of or did he express an awareness of any unsafe practice or condition?
N/A



Section A--Victim Data

1. Name <u>Dale Stamper, Jr.</u>		2. Sex <input checked="" type="checkbox"/> Male <input type="checkbox"/> Female		3. Social Security Number <u>229-26-2240</u>	
4. Age <u>56</u>		5. Job Classification <u>Utility Man</u>		7. Total Mining Experience <u>16 years</u>	
6. Experience at this Classification <u>13 years</u>		9. Victim's Experience at this Activity <u>13 years</u>		10. Was victim trained in this task? <u>Yes</u>	
8. What activity was being performed at time of accident? <u>Utility Man</u>					

Section B--Victim Data for Health and Safety Courses/Training Received (related to accident)

	Date Received
11. Annual Refresher Training (Including Hazard Recognition, Self	12/82
12. Rescue Devices, Mine Gases and Ventilation)	
13.	
14.	

Section C--Supervisor Data (supervisor of victim)

15. Name <u>Ernest Hall</u>		16. Certified <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	
17. Experience as Supervisor <u>8 months at McClure No. 1 Mine</u>		18. Total Mining Experience <u>8 years</u>	

Section D--Supervisor Data for Health and Safety Courses/Training Received (related to accident)

	Date Received
19. Annual Certified Persons Training	6/83
20.	
21.	
22.	

23. When was the supervisor last present at accident scene prior to the accident? <u>Present at time of accident.</u>	24. What did he do when he was there? <u>Unknown (he was killed in the explosion).</u>
--	---

25. When was he last in contact with the victim? <u>Unknown</u>	26. Did he issue instructions relative to the accident? <u>N/A</u>
27. Was he aware of or did he express an awareness of any unsafe practice or condition? <u>N/A</u>	



Section A—Victim Data

1. Name 2. Sex 3. Social Security Number

Miles Wedden Sutherland (Injured) Male Female 230-34-7812

4. Age 5. Job Classification

51 Roof Bolting Machine Operator

6. Experience at this Classification 7. Total Mining Experience

1½ years 27 years
8. What activity was being performed at time of accident? 9. Victim's Experience at this Activity 10. Was victim trained in this task?

Roof Bolting 1½ years Yes

Section B—Victim Data for Health and Safety Courses/Training Received (related to accident) Date Received

11. Annual Refresher Training - (Including Hazard Recognition, Self 12/82

12. Rescue Devices, Mine Gases and Ventilation)

13.

14.

Section C—Supervisor Data (supervisor of victim)

15. Name 16. Certified

Ernest Hall Yes No

17. Experience as Supervisor 18. Total Mining Experience

8 months at McClure No. 1 Mine 8 years

Section D—Supervisor Data for Health and Safety Courses/Training Received (related to accident) Date Received

19. Annual Certified Persons Training 6/83

20.

21.

22.

23. When was the supervisor last present at accident scene prior to the accident? Present at time of accident.
24. What did he do when he was there? Unknown (he was killed in the explosion)

25. When was he last in contact with the victim? 26. Did he issue instructions relative to the accident?

Unknown N/A

27. Was he aware of or did he express an awareness of any unsafe practice or condition?

N/A



Section A—Victim Data

1. Name <u>Forrest C. Riner, Jr.</u>	2. Sex <input checked="" type="checkbox"/> Male <input type="checkbox"/> Female	3. Social Security Number <u>226-22-9494</u>
4. Age <u>58</u>	5. Job Classification <u>Foreman</u>	
6. Experience at this Classification <u>17 years</u>		7. Total Mining Experience <u>38 years</u>
8. What activity was being performed at time of accident? <u>Departing from the 2 Left Section</u>	9. Victim's Experience at this Activity <u>17 years</u>	10. Was victim trained in this task? <u>Yes</u>

Section B—Victim Data for Health and Safety Courses/Training Received (related to accident)

11.	Date Received
<u>Annual Certified Persons Training</u>	<u>12/82</u>
12.	
13.	
14.	

Section C—Supervisor Data (supervisor of victim)

15. Name <u>Ronald Sluss</u>	16. Certified <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No
17. Experience as Supervisor <u>4½ years</u>	18. Total Mining Experience <u>10 years</u>

Section D—Supervisor Data for Health and Safety Courses/Training Received (related to accident)

19.	Date Received
<u>Annual Certified Persons Training</u>	<u>12/82</u>
20.	
21.	
22.	

23. When was the supervisor last present at accident scene prior to the accident? <u>6/21/83 - 7:45 p.m.</u>	24. What did he do when he was there? <u>Assisted Ernest Hall, Forrest Riner, Jr., and Luther McCoy in repairing conveyor belt feeder chain.</u>
---	---

25. When was he last in contact with the victim? <u>6/21/83 7:45 p.m.</u>	26. Did he issue instructions relative to the accident? <u>None</u>
--	--

27. Was he aware of or did he express an awareness of any unsafe practice or condition?
No